TEKWĂLL

Installation Guide


Step 1.

Making sure you have a clean protected work surface and lay the TekWall panel face down.

Step 2.

Measure area and cut TekWall to suit.









Contents: TekWall Board

Vertical grain direction!





Step 3.

Apply good quality bonding

adhesive evenly to the rear face
of the TekWall.

Step 4.

Ensuring a vertical grain direction apply even pressure across the TekWall.

Optional contents only




In the event of visible bare edges use L Section TekWall profile. Fit as per instructions below

Step 1.

Measure the length required and cut the L Section TekWall profile to suit.


Step 3.

Carefully prise the edge of TekWall away from the wall creating a gap. Slide the L Section TekWall profile in place re-applying pressure





Back edge (flush with wall)



Step 2.

Apply a thin layer of bonding adhesive to the inside face of the L Section TekWall profile.

If fitting a bottom rail ensure the L Section profile is securely screwed to the wall before fitting the TekWall.



